JAX™

Materials Safety Data Sheet

FLEMISH GRAY-BLACK BRASS, BRONZE & COPPER DARKENER

I PRODUCT IDENTIFICATION

TRADE NAME (AS LABELED): **JAX FLEMISH GRAY-BLACK BRASS, BRONZE AND COPPER DARKENER**
CHEMICAL NAMES, COMMON NAMES: NONE
SYNONYMS: NONE
MANUFACTURER'S NAME: JAX Chemical Company, Inc.
ADDRESS: 78-11 267th Street, Floral Park, New York 11004
BUSINESS PHONE: 718-347-0057

II HAZARDOUS INGREDIENTS

CHEMICAL NAME	CAS #	% w/w	EXPOSURE LIMITS IN AIR TLV ACGIH	PEL OSHA
Hydrochloric Acid	7647-01-0	> 1.0	5 ppm(C)	5 ppm(C)
Tellurium Dioxide	7446-07-3	> 0.1	0.1 mg/m^3	none

THE REMAINING 99 % INGREDIENTS ARE NON-HAZARDOUS

III PHYSICAL PROPERTIES

VAPOR DENSITY: NO DATA
EVAPORATION RATE (WATER = 1): SIMILAR TO WATER
SPECIFIC GRAVITY: 1.02
MELTING POINT or RANGE: LESS THAN 32° F
SOLUBILITY IN WATER: SOLUBLE
BOILING POINT: GREATER THAN 212° F
VAPOR PRESSURE, mm Hg @ 20 C: NO DATA
APPEARANCE & COLOR: CLEAR LIQUID
pH: 1.1

HOW TO DETECT THIS SUBSTANCE (warning properties): At room temperature this product is a clear liquid with no odor. No unusual warning properties.

IV FIRE and EXPLOSION

THIS PRODUCT IS NON-FLAMMABLE AND NON-COMBUSTIBLE

FLASH POINT, F (method): N/A
AUTOIGNITION TEMPERATURE, F: N/A
FLAMMABLE LIMITS in air by volume, %: lower N/A upper N/A
FIRE EXTINGUISHING MATERIALS:
water spray: OK carbon dioxide: OK foam: OK

dry chemical: OK halon: OK other:

SPECIAL FIRE FIGHTING PROCEDURES: If involved in fire, use water spray. Fire Fighters must use Self Contained Breathing Apparatus.

UNUSUAL FIRE & EXPLOSION HAZARDS: Product may decompose at high temperatures to form toxic gases.

V HEALTH HAZARD INFORMATION

SYMPTOMS OF OVER EXPOSURE by route of exposure:
INHALATION: May cause upper respiratory irritation.