

## E-POX-EE KLEENER<sup>tm</sup>

## Hand Kleener for Removing Resins & More!

E-POX-EE KLEENER ™ is a unique industrial hand cleaner made especially for removing unreacted liquid epoxy, polyester, urethanes and other resins from the skin. It will also remove liquid paint, lacquer and grease.

Directions for Best Results -

## DO NOT WET HANDS BEFORE USING

- 1. Dispense a liberal amount of Kleener onto the hands.
- 2. Work well into resin contaminated areas.
- 3. Wash hands with soap and water.
- 4. Repeat as necessary.

## Safety First!

- For Industrial Use Only Keep Away From Children
- If ingested, contact **Poison Control** in USA;1-800-222-1222 You Can Also Call; **Chem-Tel** in USA; 1-888-255-3924
- Do not use in proximity to flame or ignition sources. Contains Mineral Spirits.
- Store and use at room temperature.
- Do not use in proximity to the eyes. If eye contamination occurs, flush eyes with water for 15 minutes and seek medical attention.
- Refer to Material Safety Data Sheet available at <u>www.mann-release.com</u>

2000 Saint John St. \* Easton, PA 18042 USA Tel. (610) 252-5800 \* Fax. (610) 252-6200 www.mann-release.com